

THE BOEING COMPANY - SANTA SUSANA FIELD LABORATORY
CLOSURE PLAN - RADIOACTIVE MATERIALS HANDLING FACILITY




Plate 2 - View of the interior Storage Area of Building 4022




Plate 3 - View of Vault opening in Building 4022. (Ventilation port can be seen in center of photograph)




Plate 4 - View of interior of Vault within Building 4022. (Drums of higher activity low level and transuranic wastes are shown)