

Explanation

- Chatsworth Monitoring Well
- Chatsworth Extraction Well
- Property Boundary Line
- Fault and/or Shear Zone
- 1839.07 Elevation of Static Water Level, in feet above Mean Sea Level.
- Contour of Equal Water Level Elevation, in feet above Mean Sea Level. Contour interval 50 feet.
- Legend for geology: Refer to Figure 3, Geologic Map, in Haley & Aldrich's "Report on the Annual Groundwater Monitoring, 2003, Santa Susana Field Laboratory, Ventura County, California," February 27, 2004.
- KUCC Geologic Unit
- Marker Bed
- KLCS Geologic Unit
- [344] Tritium Activity (pCi/l); ND = Not Detected
- 4009 Radiological Facility
- Location of Recently Constructed Well
- Location of Recently Abandoned Well

0 355 710 1,420 Feet

HALEY & ALDRICH

UNDERGROUND ENGINEERING & ENVIRONMENTAL SOLUTIONS

THE BOEING COMPANY
ROCKETDYNE PROPULSION & POWER
SANTA SUSANA FIELD LABORATORY

ACTIVITY OF TRITIUM IN GROUNDWATER (pCi/l), FEBRUARY / MARCH 2004

SCALE AS SHOWN

MAY 2004

FIGURE 2

97_SSFL_AREA_IV_RAD_WELLS